
Changes for V1.3.6.30532.zip

Date:2016-12-24

测试方式: 系统测试+压力测试+工厂生产测试

*Commor

Interim firmware for A1X, if the firmware is V1.xxx upgrade to the V2.xxx, need first upgrade to the interim firmware.