
Changes for A41-V1.1.7.b7fcf.fw

Date:2017-5-2

测试方式: 系统测试+压力测试+工厂生产测试

*Common

Interim firmware for A41, when upgrade to the 2.xxx, it needs first upgrade to this firmware.